

TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.
10 North Martingale Road, Ste 575
Schaumburg, IL 60173
Tel (847) 925-0888 Fax (847) 925-0899
<http://www.t-yuden.com>

DISCONTINUATION NOTICE

DATE: March 1, 2011
RE: Discontinuation Notice of CCFL Inverters for Backlight in LCD Modules
REF NO.: UTY-DN11-03

Taiyo Yuden (U.S.A.), Inc. hereby gives notice that following CCFL inverters will be discontinued and no longer offered by Taiyo Yuden.

The orders will be accepted for these parts through January 31, 2012 for deliveries through May 31, 2012 . Orders for these components received after the last time buy date - January 31, 2012 - are Non-Cancelable and Non-Returnable.

Discontinued Item
KBI-B02D-RH
KLS-150A-RH
KLS-170A-RH
LS380-RH
LS380-RHG
LS460-RH
LS530-RH
LS655-RH
LS6D0812A-RH
LS700-RH
LS720-RH
SIPF-150-RH
SIPF-200A-RH

Discontinuation Schedule

By 2012/01/31: Last-time buy orders accepted.

By 2012/05/31: Last deliveries scheduled.

If you have any questions regarding this announcement please contact Ms. Linda Suarez. Email: lsuarez@t-yuden.com

NOTE: The information in this notice is applicable only to Taiyo Yuden customers in North and South America. Discontinuation schedules and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department